ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
6

Ward Name
Thanisandra

Street ID
W1171, W1155, W1183, W1153, W1199, W1191, W0780, W

Street Name
NA, 5th Crs Panathur New Extenslon Kaverappa Lyt

Significant Landmark
Anjanadrai layout

Segment No.
6/C-W1171/S083512

Total Length (m)
570.37

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	141.92	77.628586	13.051135	77.629080	13.052322	W0970	W0782
2	106.16	77.627483	13.051181	77.627852	13.052070	W1405	W1387
3	322.29	77.625787	13.053690	77.628652	13.052926	W0387	W0759

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to road & drain at Anjanadrai layout in ward no 06 Byatarayanapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
2000000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to road & drain at Anjanadrai layout in ward no 06 Byatarayanapura Sub-Division Yelahanka zone

Job No. / Work Code
006-14-000005

Work Order No.
EE/BTP/BBMP/E-PMT/WO/299/2015-16

Work Order Date
23/03/2016

Period of Extention
90 DAYS

Defect Liability Period From
23/03/2016

Defect Liability Period To
22/03/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
Y.B.RAMESH

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.
9611118200

E-Mail ID

Field Inspection Details

Number of Trees	Any Other Information	Name
6		KRISHNAPPA
Date of Inspection	**Remarks**	
24/09/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1171, W1155, W1183, W1153,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/09/2016	24/10/2016	COMPLETED
SE	VASU K M	24/09/2016	24/10/2016	COMPLETED
EE	YARAPPA REDDY	24/09/2016	24/10/2016	COMPLETED
AEE	J N LOKESH	24/09/2016	24/10/2016	COMPLETED
AE	KRISHNAPPA	24/09/2016	24/10/2016	COMPLETED
AE	KRISHNAPPA	24/09/2016	24/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1171, W1155, W1183, W1153,